



Photo P1. Upper limit of Park Reach at Hildebrand Avenue.



Photo P2. San Antonio River in Brackenridge Park.



Photo P3. Bank Erosion in upper portion of Park Reach.



Photo P4. Forest has many invasive species.



Photo P5. Degraded riparian vegetation within Park Reach.



Photo P6. Good quality riparian habitat within Park Reach.



Photo P7. Drop Structure in Brackenridge Park.



Photo P8. Sediment buildup with in-stream vegetation in Park Reach.



Photo P9. Mulberry Avenue bridge and iron railroad bridge.



Photo P10. Sparse riparian vegetation through golf course.



Photo P11. San Antonio River in Brackenridge Golf Course.



Photo P12. Southern end of Park Reach at U.S. Highway 281.



Photo P13. Northern limit of Catalpa-Pershing Channel.



Photo P14. Catalpa-Pershing Channel.



Photo P14. Transition from concrete to grass-lined channel.



Photo P15 Catalpa-Pershing in Brackenridge Golf Course.





Photo M1. Oblique – SART outlet.



Photo M2. Oblique – North of Confluence with San Pedro.



Photo M3. Oblique – Confluence with San Pedro



Photo M4. Oblique - Old San Juan Dam.



Photo M5. Oblique – Espada Dam.



Photo M6. Oblique – North of Ashley Road.



Photo M7. Oblique – North of I.H. 410.



Photo M8. Oblique – I.H. 41.



Photo M9. Upper limit of Mission Reach at Lone Star Blvd.



Photo M10. Near City Public Services bridge (Sta. 2101.60).



Photo M11. Sheet pile check dam #3 (Sta. 2075+80).



Photo M12. Confluence with San Pedro Creek (Sta. 2060+50).



Photo M13. Active head cutting near Sta. 2044+00.



Photo M14. Invasive vegetation near Sta. 2024+40.



Photo M15. Storm drain near Sta 1996+00



Photo M16. Golf course storm drain [west] (Sta. 1993+30)



Photo M17. Storm drain [east] from golf course (1993+20).



Photo M18. Concrete sill grade structure (Sta. 1978+70).



Photo M19. Storm drains near Sta. 1978+00.



Photo M20. Floodway downstream of Southcross St.



Photo M21. Storm outlet near Sta. 1937+00.



Photo M22. North end of Old San Juan Dam (Sta. 1900+20).



Photo M23. Eroding bank below the Old San Juan Dam near Sta. 1894+20.



Photo M24. A dewatered segment upstream of Six Mile Creek



Photo M25. Dam grade structure near Sta. 1877+00.



Photo M26. Erosion near I.H. 410 bridge (Sta. 1741+00).



Photo M27. Downstream of Six Mile Creek bypass.



Photo M28. Pedras Creek outfall (Sta. 1783+40).



Photo M29. Return of old river channel (Sta. 1774+60).



Photo M30. Camino Coahuilteca crossing (Sta. 1727+60)



Photo M31. Maintained floodway of SACIP.



Photo M32. Eroded bank slope of floodway.



Photo M33. Unidentified storm drain.



Photo M34. Headcutting and scour.



Photo M35. Unidentified storm drain.



Photo M36. Unidentified storm drain.



Photo M37. Unidentified storm drain.



Photo M38. Unidentified storm drain.