

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: **Picker**

Project Name: **Angio Omnicon upgrade**

Installation Name: **Fort Gordon, GA**

Contract-DO Number: **66-73**

Contract Number: **SP0200-96-D-8066**

Date: **11Aug, 1999**

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

**Performed overhead inspection with contractor and hospital maintenance staff. There are several duct joints that need re-sealing with mastic.
Sheet rock joints in control room are being finished.**

% **Continued on next page__**

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

