

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: J.J. Kirlin

Project Name: Replace Dielectric Unions

Installation Name: Fort Gordon, GA

Contract-DO Number: 25-0085

Contract Number: DACA01-98-D-0025

Date: August 28, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O.)

Comments:

Contractor continued work on the 10th floor. Repaired a leak on a box on the 8th floor

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

