

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: J.J. Kirlin

Project Name: Replace Dielectric Unions

Installation Name: Fort Gordon, GA

Contract-DO Number: 25-0085

Contract Number: DACA01-98-D-0025

Date: Sept 27, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O.)

Comments:Contractor continues to work on the 9th floor.

Some of the ceiling grid support came loose during the night. Contractor repaired it this morning.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

