

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Doors

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0099

Contract Number: DACA01-98-D-0024

Date: Oct 11, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Contractor hung sheet rock and mudded at door 1G-04

Contractor Name: Lloyd South Signature: _____US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom