

# DAILY QUALITY ASSURANCE REPORT

PAGE \_\_\_\_ OF \_\_\_\_

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0100

Contract Number: DACA01-98-D-0024

Date: August 28 , 2000

(USE SEPARATE REPORT FOR Each D.O./P.O )

## Comments:

Installing fire damper on the first floor

Inspected fire wall penetrations on the 13<sup>th</sup> and 12<sup>th</sup> floors. About 5 deficiencies were noted and corrected. We found several places where fire dampers were needed in ducts but none were identified on the Newcomb and Boyd survey. Contractor is making a list of such items to give to us at the end of the project.

.

Name: Lloyd South  
US Army Corps of Engineers  
Quality Assurance Representative  
Supporting MedCom

Signature:

