

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0100

Contract Number: DACA01-98-D-0024

Date: Sept 25 , 2000

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Installing exit light at various locations
Moved 4in electrical conduit in preparation for installing 42in fire damper.
Damper replacement is scheduled for next Monday.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

