

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: October 30, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O.)

Comments:Began work on the 10th floor west end.

Prepped area for painting grid. Tried several methods for applying paint to grid. Not too satisfied with results. Will try some new equipment tomorrow.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

