

**DAILY QUALITY ASSURANCE REPORT**

PAGE \_\_\_\_ OF \_\_\_\_

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: October 31, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O.)

**Comments:**

Painted some ceiling grid using a new gun and tip. Application looks good. Continued painting grid. Electrician working on exit lights. Removed two from wall location and hung from ceiling. Patched holes in wall.

Name: Lloyd South  
US Army Corps of Engineers  
Quality Assurance Representative  
Supporting MedCom

Signature:

