

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: November 01, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Removed some of the old ceiling tile and disposed in dumpster at rear of building. Put in some new tile. Working space is very, very limited in many areas. Some of the new tile will have to be replaced because it was damaged during installation. Electrician continues to work on exit lights.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

