

WEEKLY QUALITY ASSURANCE REPORT

PAGE ____

OF__

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending November 02, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

General Comments:Started work on the 10th floor west end.**Work performed:**

Painted existing ceiling grid. Removed old ceiling tile. Installed new ceiling tiles.
Relocated exit lights that were mounted in a wall. Moved them to a ceiling location. Patched holes. Tied exit lights into hospital life safety power.

Percent complete (if applicable) 20 %**Safety violations / Corrective measures taken:**

Safety meeting held

Work Scheduled:**Indicate Attachments:**

% Daily QA Reports

% Schedule assessments

% Inspection Checklist

% Other

% Safety Tool Box Meeting

% Minutes of Meetings

% Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature: Lloyd South