

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: November 07, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Continue to paint ceiling grid and replace ceiling tile on 10th floor
Electrician replaced 4 exit lights

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

