

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: November 16, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O.)

Comments:

Replacing ceiling tile on 11th floor. Replacing exit lights on 10th and 11th floor.
Working on punch list for 10th floor.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

