

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety-Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: December 12, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Punching out work on the 12th floor. Replacing grid and tile on the 13th floor.
Started painting grid on the 9th floor east end.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

