

WEEKLY QUALITY ASSURANCE REPORT

PAGE ____

OF__

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending December 07, 2000

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

General Comments:. Completed punch out of ceiling grid and tile for the 13th floorBegan work on the 9th floor.

Replacing exit lights on 10 through 13

Work performed:Finished work on the 13th floor. Started work on the 9th floor.Percent complete (if applicable) 30%**Safety violations / Corrective measures taken:**

Safety meeting held

Work Scheduled:**Indicate Attachments:**

% Daily QA Reports

% Schedule assessments

% Inspection Checklist

% Other

% Safety Tool Box Meeting

% Minutes of Meetings

% Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedComSignature: Lloyd South