

**WEEKLY QUALITY ASSURANCE REPORT**

PAGE \_\_\_\_

OF \_\_\_\_

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending January 11, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O ./ Contract)

**General Comments:****Work performed:**

Inspected finished work on the 12<sup>th</sup> and 9 east. Deficiencies corrected  
 Replaced ceiling grid on the 7<sup>th</sup> 8<sup>th</sup> and 9<sup>th</sup> floors  
 Painted ceiling grid on the 7<sup>th</sup> and 8<sup>th</sup> floors.  
 Replaced ceiling tile on the 9<sup>th</sup> floor  
 Replaced exit lights on the 7<sup>th</sup> 8<sup>th</sup> and 9<sup>th</sup> floors.

Percent complete (if applicable) 50%**Safety violations / Corrective measures taken:**

Safety meeting held

**Work Scheduled:****Indicate Attachments:**

% Daily QA Reports

% Schedule assessments

% Inspection Checklist

% Other

% Safety Tool Box Meeting

% Minutes of Meetings

% Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers  
 Quality Assurance Representative  
 Supporting MedCom

Signature: Lloyd South