

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: January 15, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Painting grid on the 5th and 7th floor
Replacing tile on the 7th and 8th floor
Replacing exit lights on the 8th floor

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

