

WEEKLY QUALITY ASSURANCE REPORT

PAGE ___ OF ___

Name of Contractor: Global Engineering

Project Name: Life Safety-- Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending January 18, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O ./ Contract)

General Comments:**Work performed:**

Inspected finished work on the 8th floor. Deficiencies corrected
 Replaced ceiling grid on the 4th, 5th and 7th floors
 Painted ceiling grid on the 5th and 7th floors.
 Replaced ceiling tile on the 4th and 7th floor
 Replaced exit lights on the 4th floor.

Percent complete (if applicable) 50 %**Safety violations / Corrective measures taken:**

Safety meeting held

Work Scheduled:**Indicate Attachments:**

% Daily QA Reports

% Schedule assessments

% Inspection Checklist

% Other

% Safety Tool Box Meeting

% Minutes of Meetings

% Assistance provided to Facility Manager

Name: **Lloyd South**

(Printed)

Signature: **Lloyd South**

US Army Corps of Engineers
 Quality Assurance Representative
 Supporting MedCom