

WEEKLY QUALITY ASSURANCE REPORT

PAGE ___ OF ___

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending February 22, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O ./ Contract)

General Comments:

Work performed:

Replaced ceiling grid on the 1st and 2nd floors.
Painted ceiling grid on the 1st and 2nd floors.
Replaced ceiling tile on the 1st and 2nd floors.
Replaced exit lights on the 1st and 2nd floors.

Percent complete (if applicable) 50 %

Safety violations / Corrective measures taken:

Safety meeting held

Work Scheduled:

Indicate Attachments:

% Daily QA Reports % Schedule assessments % Inspection Checklist % Other

% Safety Tool Box Meeting % Minutes of Meetings % Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature: Lloyd South