

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: February 27, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O)

Comments:

Replaced some ceiling grid on the 2nd and 5th floor.

Installing ceiling tile on the 2nd floor

Replacing exit lights on the 2nd floor

Painted grid on the 3rd floor.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

