

WEEKLY QUALITY ASSURANCE REPORT

PAGE ___ OF ___

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending March 01, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

General Comments:**Work performed:**

Replaced ceiling grid on the 2nd floor.
Painted ceiling grid on the 3rd floor.
Replaced ceiling tile on the 2nd and 5th floors.
Replaced exit lights on the 3rd floor.

Percent complete (if applicable) 50 %**Safety violations / Corrective measures taken:**

Safety meeting held

Work Scheduled:**Indicate Attachments:**

% Daily QA Reports % Schedule assessments % Inspection Checklist % Other

% Safety Tool Box Meeting % Minutes of Meetings % Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature: Lloyd South