

DAILY QUALITY ASSURANCE REPORT

PAGE ____ OF ____

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls --Phase 2

Installation Name: Fort Gordon, GA

Contract-DO Number: 24-0128

Contract Number: DACA01-98-D-0024

Date: March 14, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O.)

Comments:

Replaced some ceiling grid on the 3rd and 2nd floors
Installing ceiling tile on the 3rd and 5th floors
Replacing exit lights on the 3rd floor
Painted grid on the 9th floor.

Name: Lloyd South
US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

Signature:

