

WEEKLY QUALITY ASSURANCE REPORT

PAGE ___ OF ___

Name of Contractor: Global Engineering

Project Name: Life Safety--Walls Phase 2

Installation Name: Fort Gordon, GA, USA

Contract/DO/PO Number: 24-128

Contract Number: DACA01-98-D-0024

Date: week ending March 22, 2001

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

General Comments:**Work performed:**

Replaced ceiling grid on the 5th and 9th floors.
 Painted ceiling grid on the 5th & 9th floors.
 Replaced ceiling tile on the 5th and 9th floors.
 Replaced exit lights on the 1st and 2nd & 5th floors.

Percent complete (if applicable) 80 %**Safety violations / Corrective measures taken:**

Safety meeting held

Work Scheduled:**Indicate Attachments:**

%o Daily QA Reports %o Schedule assessments %o Inspection Checklist %o Other

%o Safety Tool Box Meeting %o Minutes of Meetings %o Assistance provided to Facility

Manager

Name: Lloyd South

(Printed)

US Army Corps of Engineers
 Quality Assurance Representative
 Supporting MedCom

Signature: Lloyd South