

DAILY QUALITY ASSURANCE REPORT

PAGE _ OF _

Name of Contractor: J. J. KIRLIN

Project: REPLACE ROOF

Location of Work: FT. LEONARD WOOD, Mo Contract/DO/PO Number : DACA01-98-D-0025-90

(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract)

Date: June 22, 2001

Work performed by contractor:

Installing insulation & roofing on north side of building.

Personnel on Site:

Superintendent / Quality Control: Ken Porting (1)

Workers: Kirlin (1) Kirberg Roofing (13) VAC_IT_ALL (0)

Significant Equipment on Site:

Crane, kettle

Deliberate Inspections made by QA Representative:

Roofing ongoing.

Weather Conditions that effected the site:

No weather delay today.

Safety violations / Corrective measures taken:

No safety violations observed today.

Work Scheduled:

1. New roof installation

Coordination with Facility Manager:

None required this date.

Name: Robert Price

Signature :

US Army Corps of Engineers
Quality Assurance Representative
Supporting MedCom

